Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight *DHR Id#:* **046-0018**

Resource Identification

Holland House

Property Name(s) ..... House Site {Historic}
Property Date: 1830
Address(s): ..... Route 641 {Current}
County/Independent City. Isle Of Wight
City: .....
State, Zip: ..... Virginia
USGS Quad Name: ..... HOLLAND

National Register Eligibility Status
Property is Historic (50 years or older)

Property has not been evaluated

Resource Description

Primary Resource Exterior Component Description:

WUZIT Count:

No	Wuzit Types	Historic?
1	Archaeological Site	Historic

NR Resource Count:

Individual Resource Information

WUZIT: ..... Archaeological Site
Est. Date of Construction: .... 1830 {VDHR Survey File}
Primary Resource? ..... Yes
Architectural Style: ..... Other
Interior Plan Type: .....
Accessed? .....
Number of Stories: 0.0
Condition: ..... Demolished
Threats to Resource: .....

Description: Architecture Summary The original structural system was a frame single dwelling with clapboarding. It had 1.5 stories with a gableroof. The foundation was brick with American bond treatment. End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: End Interior Description

Cemetery Information

Bridge Information

National Register Eligibility Information *(Intensive Level Survey)*

Historic Context(s): ..... Domestic

Bibliographic Documentation

Ownership Information

Graphic Media Documentation

Cultural Resource Management (CRM) Events

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight ***DHR Id#:*** **046-0018**

CRM Event # 1,
Cultural Resource Management Event: ..... HABS Inventory
Date: 1958/10/99
Organization or Person: ..... Robert Wiggins
CRM Event Notes or Comments: .....

46-18



/VHI/P/15/0081.jpg

To print this page hit Ctrl+P (Windows) or Command+P (Mac)

This image is from the Virginia Historical Inventory Photographs, Works Progress Administration Collection at the Library of Virginia.

This collection is located in the Picture Collection at the Library of Virginia.

You may order prints from this collection by contacting LVA's Picture collection by email or fax. Please be certain to include the **name** of the collection and the **image numbers** (not the URL) when making picture requests.

If these images will be used or reproduced in any format, you must get permission from the Picture Collection (http://www.lva.lib.va.us/whatwehave/photo/picture.htm)

- picture@lva.lib.va.us
- (804) 692-3709 FAX

WORKS PROGRESS ADMINISTRATION OF VIRGINIA
HISTORICAL INVENTORY

COUNTY: Isle of Wight

4

CLASS: Home

Photograph

SEE PICTURE COLLECTION

--- C O U N C I L L H O M E ---

This write-up is a part of the Virginia W. P. A. Historical Inventory Project sponsored by the Virginia Conservation Commission under the direction of its Division of History. Credit to both the Commission and W. P. A. is requested for publication, in whole or in part. Unless otherwise stated, this information has not been checked for accuracy by the sponsor.

Research made by
Florence Jordan,
Benn s Church, Virginia.

May 27, 1937.

1. SUBJECT:

Councill Home.

2. LOCATION:

1/2 mile west of Carrsville, Virginia, on Route # 58, thence 1.4 miles north on Route # 614, thence 1/2 mile east of Route # 614.

3. DATE:

About 1830. (1842 on one chimney.)

4. OWNERS:

Godwin Councill
Jesse D. Councill 1901
B. P. Councill) 1937
Mrs. Jessie Pondwhite, Wakefield, Virginia)

5. DESCRIPTION:

This is a story and a half frame house, located in a grove of elm trees. It has twenty windows, with four, nine, twelve and eighteen panes, all eight by ten inches, of which eleven are dormers, across the front, with blinds. The front porch is about four steps from the ground. The doors have six panels and are thought to be made of poplar wood. The two brick chimneys are wide, and on each end. The date 1842 is on one chimney.

The interior needs cleaning and painting. The wainscoting and wide floors, and hand-carved mantels are very pretty. There are six small rooms and two halls. The stairway ascends from the back of the hall.

The two room kitchen, off from the house, is still being used. It has a little brick house on the end. The fireplace is about eleven feet wide and still has the hooks and hangers in it.

6. HISTORICAL SIGNIFICANCE:

The Councill's owned slaves , as shown by the slave houses.

7. ART:

Photograph

8. SOURCES OF INFORMATION:

Informants: Mr. and Mrs. H. B. Duck, Carrsville, Virginia.
Miss B.P.Council.

Court Records, Clerk's Office, Isle of Wight County, Virginia.

IW-4

3686

ARCHITECTURAL DESCRIPTION OF BUILDING CALLED FOR IN
5-A, of BULLETIN 3400

Name of Building Councill Home.

EXTERIOR

1. Building Plan Rectangular and shed room on back. Cellar None)
2. No. of stories: 1 1/2 Attic classed as 1/2 story.
3. Material: Brick ( ) Frame (x) Stone ( ) Log ( )
4. If brick, state what bond: Flemish ( ) English ( ) Common ( ) Other ( )
5. Kind of roof: Hip ( ) Gabled (x) Gambrel ( ) Lean-to ( ) Deck ( )
6. If church, describe or draw sketch of roof on reverse side.
7. Roof Material: Slate ( ) Shingle (x) Metal ( ) Tile ( )
8. Chimneys: Number (2) Brick (x) Stone ( ) Location One on each end.
9. Weatherboarding: Unpainted. Beaded ( ) Plain (x)
10. Cornices: Plain or Elaborate Plain Material Wood.
11. Windows: Number (20) Size and number of panes 18 panes 8" x 10".
9 panes 8" x 10".
4 panes 8" x 10".
12 panes 8" x 10".
15 panes 8" x 10".
12. Shutters: Describe: Stationary slats.
13. Dormers: Number, and Shape of roof Eleven dormers extend out from roof.
14. Porch: One story front porch, approximate size 10" x 10".
15. Type of Entrance: Six panek front door.
16. Columns: Doric (x) Ionic ( ) Corinthian ( ) Square ( )

INTERIOR

17. No. of Rooms: (6) Large ( ) Small (x) Approximate ceiling height 10" 7" up stair
18. Stairway: Open String (x) Closed String ( ) Describe: One flight, simple square balusters, square newel, pine hand rail, round, painted.
19. Cellar: Describe None.
20. Doors: Style and type of wood Six panel, unpainted doors, made of poplar.
21. Walls: Panelled, papered or painted Wood wainscoting and plastered.
22. Interior Cornices None.
23. Hardware: Locks and hinges Iron outside locks, common iron outside hinges.
24. Floors: Wide pine flooring of varying widths.
25. Mantels: Hand-carved mantels.
26. Misc: For fourteen years, H. B. Duck has lived here.
27. Present condition: and state if spoiled architecturally by remodelling: No. Not good.
28. Does occupant seem to appreciate old architectural features? Yes.

Your Name Florence Jordan.